 HÄSSLEHOLM MILJÖ AB VI BRINER FÖR EN HÅLLBAR FRAMTID	Document name		
	Appendix E: Specific requirements for Sewage Treatment Plant		
Issued by The safety committee	Approved by/manager Sven Carlsson	Date 2020-12-01	Edition 01

Appendix E Specific requirements for Sewage Treatment Plant

General

- The speed limit throughout the area is 20 km/h
- Defibrillator is located at marked places: first floor in the office building
- First aid equipment are located at the following marked places: first floor in the office building, in the workshop and in the machine building
- At study visits, the supervisor will provide vest
- Visitors/contractors at the facility shall wear at least reflective vest or high visibility clothing when working/visiting the facility. At some specific areas where other clothing is needed, the personnel of HMAB shall inform about this before work begins.
- Photographing and filming at the facility is only permitted after permission from responsible visitor attendant.
- Smoking is permitted only at unpaid breaks and outside fenced area.
- Signs, guardrails and obstructions shall be observed and followed.
- At the facility, following risk areas exists amongst others: Gas plant, zones with flammable and explosive goods, sewage treatment plant (with chemicals) and likewise (see map). These are areas with high risk of fire and explosion. Special care is required against sparking and open fire.


Personal protective equipment

- Safety shoes shall always be used during work. Exceptions are made for:
 - Shorter visits at the workplace
 - Office work
 - Laboratory work
- Safety helmet shall be used during plumbing work, blasting work, crane work and work performed at level differences.
- Safety goggles shall be used during:
 - Cutting work
 - Usage, preparation and handling of chemicals that pose a risk for the eyes
 - Vegetation clearing
- Visitors/contractors shall follow given instructions regarding usage of personal protective equipment

Specific areas

- So-called hot works occur at the facility. This requires permission and only permit managers can issue these.
- EX zones are marked on the map. Outside each area there is a yellow and black sign that draws attention to the risk of explosive atmosphere. The following applies here:
 - Leave cellphones, keys, tools, flashlights etc., meaning such things that can cause sparks while used or if dropped, outside the area.
 - Get an idea of the fastest and most secure escape route and make sure that it is not blocked before entering.

> A part of the Municipality of

 HÄSLEHOLM MILJÖ AB VI BRINNER FÖR EN HÅLLBAR FRAMTID	Document name Appendix E: Specific requirements for Sewage Treatment Plant		
	Issued by The safety committee	Approved by/manager Sven Carlsson	Date 2020-12-01


- Before entering in the specific area, make sure that gas leakage is not present.
- During the visit, if you feel a pungent odor, dizziness or nausea, exit the area hastily through the safest escape route.

If you are the slightest unsure, you should contact the **MANAGER**, meaning the person at the facility that is responsible for the safety regarding the handling of gas and work in risk areas.


Overview maps

Hässleholm Sewage Treatment Plant

Hovdalavägen 51, 281 35 Hässleholm



> A part of the Municipality of

 HÄSSLEHOLM MILJÖ AB <small>VI BRINER FÖR EN HÅLLBAR FRAMTID</small>	Document name Appendix E: Specific requirements for Sewage Treatment Plant		
Issued by The safety committee	Approved by/manager Sven Carlsson	Date 2020-12-01	Edition 01

I have read and understood the meaning of the above:

Name (text) and company

Date and signature

Signed part of document is saved by HMAB

> A part of the Municipality of